

Component - Plastics

SHUMAN PLASTICS INC

E80143 (M)

(B - cont. from A card)

Polystyrene (PS), furnished in the form of pellets.										
SP-800	All	1.5	94HB	50	50	50	—	—	—	—
Acrylonitrile-butadiene-styrene (ABS), furnished in the form of pellets.										
SP-790	All	2.5	94V-0	60	60	60	2	0	3	6
		3.0	94-5VA	60	60	60	—	—	—	—
SP-791	All	2.5	94V-1	80	70	80	2	0	3	6
Polycarbonate (PC), furnished in the form of pellets.										
SP9XX(f1)	All	1.5	94V-2	80	80	80	—	—	—	—

Reports: October 12, 1992; October 16, 1992; October 13, 1992; September 30, 1996.

Replaces E80143B dated September 3, 1993.

342904001

N7047

Underwriters Laboratories Inc.®

(Cont. on C card)

011/0091860

QMFZ2

December 20, 1990

Component - Plastics

SHUMAN PLASTICS INC

E80143 (M)

(C - cont. from B card)

(f1) Suitable for outdoor use with respect to exposure to Ultraviolet Light, Water Exposure and Immersion in accordance with UL 746C.

Marking: Company name and material designation on part, container or wrapper.

See General Information Preceding These Recognitions.

UL94 small-scale test data does not pertain to building materials, furnishings and related contents. UL94 small-scale test data is intended solely for determining the flammability of plastic materials used in the components and parts of end-product devices and appliances, where the acceptability of the combination is determined by ULI.

Report: May 29, 1987.

Replaces E80143C dated June 2, 1989.

342904001

Underwriters Laboratories Inc.®

D11/0167590

46

QMFZ2
Component - Plastics

September 3, 1993

SHUMAN PLASTICS INC
35 NEOGA ST, DEPEW NY 14043

E80143 (M)
(A card)

Mtl Deg	Col	Min Thk mm	UL94 Flame Class	Elec	RTI		H W I	H A I	H V T R	D 4 9 5	C T I
					with Imp	Mech w/o Imp					
Acrylonitrile-butadiene-styrene/polyvinyl chloride (ABS/PVC), furnished in the form of pellets.											
SP-780	BK	1.5	94V-1	80	80	80	1	—	—	—	—
		2.5	94V-0	80	80	80	0	—	—	—	—
Polyphenylene ether copolymer (PPE), furnished in the form of pellets.											
SP211	All	1.5	94V-0	50	50	50	0	2	—	—	—
		3.0	94V-0, 94-5VA	50	50	50	0	1	4	6	1

Reports: October 14, 1992; October 19, 1992.

Replaces E80143A dated October 9, 1992.

(Cont. on B card)

342904001

H7047

Underwriters Laboratories Inc.®

D11/0088887